

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3157	DATE	May 24,2013
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO. LTD.		
DESCRIPTION OF DEFECT	In the heavy-duty dump trucks, there are some vehicles that have a defect in routing of the control wire for operating dump and have the possibility of contacts of the control wire with the air tube for the rear brake due to the vibrations of the truck in running. Therefore, when users continue using the vehicle as it is, it can cause damage to such air tube and air leakage can occur, and at worst, there is the possibility that the braking ability decreases.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FV50VX	SUPER GREAT	2010-2012	57
LDG-FV50VY	SUPER GREAT	2011	2
LKG-FP54VDR	SUPER GREAT	2011-2012	4
LKG-FU50VY	SUPER GREAT	2010-2011	3
LKG-FV50VX	SUPER GREAT	2012	2
LKG-FV50VY	SUPER GREAT	2011	1
LKG-FV50VZ	SUPER GREAT	2010-2012	7
QDG-FV50VX	SUPER GREAT	2012	3
QDG-FV50VY	SUPER GREAT	2012	1
QKG-FP54VDR	SUPER GREAT	2012	1
QKG-FU50VY	SUPER GREAT	2012-2013	4
QKG-FU54VZ	SUPER GREAT	2012	1
QKG-FV50VX	SUPER GREAT	2012-2013	60
QKG-FV50VY	SUPER GREAT	2013	4
QKG-FV50VZ	SUPER GREAT	2012-2013	2
TOTAL			152