

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3170	DATE	Jun. 20 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some differentials for heavy- or medium-duty trucks, improperly processed pinion gears were assembled. If the vehicle continues to be used in this condition, the pinion gears will be seized and, in the worst case, the differential may break and the vehicle will become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-FP54VDR	「FUSO SUPER GREAT」	2012	1
QKG-FU55VZ		2012	1
TKG-FK71F		2013	1
		TOTAL	3