VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3175	DATE	Jun 18,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	have been inst adhesion stren reduced. If use peeled from th	alled without the appli- gth between the glass continues under this	noramic roof glass, the glass may ication of the primer causing the and the adhesive agent to be condition, the glass would be n the worst case scenario, the ed.

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GA3W	$\lceil \mathrm{RVR} floor$	$2010 \sim 2011$	1,893
		TOTAL	1,893