

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3197	DATE	Aug. 1, 2013
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	<p>On the power train device, since the parking rod which locks the gears of parking mechanism of an automatic transmission was assembled incorrectly, the parking rod pinch of certain rods was broken. Under these circumstances, the parking rod may be disengaged from the manual plate and even with the transmission shifted into the "park" position, the parking mechanism may not operate properly and the vehicle may move unexpectedly if the parking brake is not used.</p> <p>In case the parking rod detaches while the parking mechanism gears are locked, disengagement of gear lock may not be possible rarely. In the worst condition, the vehicle may not be moved or driven.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BRF	「LEGACY」	2013	1
CBA-GRF	「IMPREZA」		13
CBA-GVF			8
		TOTAL	22