

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3200	DATE	Aug. 1 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>In some large busses, coolant flowing through the heater hose can permeate the hose from its end due to insufficient fastening force of the clamp for securing the heater hose, causing the reinforcing strings in the hose to be dissolved by the coolant. If the hose continues to be used in this condition, it may not withstand the pressure of the coolant flowing through it due to the reduced strength, causing damage to the hose and coolant leakage. This could impair the defroster function, diminishing the view in front of the front windshield.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-MS96VP	「FUSO AERO ACE」	2010~2012	469
	「FUSO AERO QUEEN」	2010~2012	92
QRG-MS96VP	「FUSO AERO ACE」	2012~2012	204
	「FUSO AERO QUEEN」	2012~2012	19
LKG-AS96VP	「SPACEARROW A」	2010~2011	12
	「SPACEWING A」	2010~2011	5
TOTAL			801