

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3201	DATE	Aug. 1 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some middle size buses, the tightening torque of the bolts that secure the front door to the body is not sufficient. As a result, the bolts could become loose and come off, making it impossible to open or close the door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-MK27FH	「FUSO AERO MIDI」	2011~2012	16
SKG-MK27FH		2012~2013	69
		TOTAL	85