

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1960	DATE	August 30 <sup>th</sup> 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The battery-positive cable links the battery with the power distribution box supplying electric power to the vehicle. Due to the inappropriate material for metal coating and configuration of the connector of the battery-positive cable, corrosion may occur because of vehicle vibration and contact resistance may increase. This results in insufficient electric power supply from the power distribution box to the vehicle electrical components, which leads to defect on the electrical components. In worst case, engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LBA-UC20	BMW 120i Coupe	2011	39
ABA-UC30	BMW 135i Coupe	2011	79
LBA-UM20	BMW 120i Cabriolet	2011	7
LBA-KD20	BMW 320i Coupe	2011	119
LBA-KD20G		2011	12
LBA-KE25	BMW 325i Coupe	2011	24
ABA-KG35	BMW 335i Coupe	2011	50
ABA-DX35	BMW 335i Cabriolet	2011	37
		TOTAL	367

This recall was announced on March 12<sup>th</sup> 2013 as recall Gai-1912. Since additional vehicles have been found to be affected, added vehicles will be announced with this recall Gai-1960.