

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3232	DATE	September 26, 2013
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	The lift gate latch may not lock properly due to incorrect dimension of latch component caused by inappropriate manufacturing. In the worst case, the lift gate may open while vehicle in motion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-SKP2V	Mazda 「BONGO」	2012-2013	3,111
ABF-SKP2M		2012-2013	979
ABF-SKP2VN	Nissan 「VANETTE」	2012-2013	34
ABF-SKP2MN		2012-2013	1,695
		Total	5,819