

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3231	DATE	Sep. 26 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In the automatic transmission for minibuses, the snap ring clamping the clutch components will possibly drop off due to improperly machined mating section. If the fault will occur, torque will not be transmitted through the clutch, which will prevent the vehicle from running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-BE63DE	「FUSO ROSA」	2008	1
PDG-BE63DG		2008~2008	2
PDG-BE64DG		2009~2010	6
PDG-BE64DJ		2008	1
		TOTAL	10