

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	3228	DATE	Sep 26, 2013
MANUFACTURER	Toyo trailer. co., ltd		
DESCRIPTION OF DEFECT	<p>Since heat treatment of a stabilizer arm is unsuitable, there are some which are insufficient of intensity.</p> <p>Therefore, when use is continued in the state as it is, a stabilizer arm breaks, running stability is spoiled and there is a possibility that it may become impossible to run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TT22DA	Tank Semitrailer	2007~2009	5
TT25DA		2007~2008	4
TT29DA		2005	2
TT29DA1		2006	2
TT29DA3		2007	4
TT32DA		2006	2
TT32DA1		2006	1
TT32DA2		2006	1
TT32DA3		2007	4
TT33DA		2006~2007	3
TT33DA1		2007	1
TT33DA2		2007	2
TT33KA		2006	3
TT33KA1		2007	1
TT33KA2		2008	1
TV25KA		Van Semitrailer	2006
TV24KA	2006~2007		2
		TOTAL	39