

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1965	DATE	Sep 26, 2013
MANUFACTURER	Toyo trailer. co., ltd		
DESCRIPTION OF DEFECT	<p>Since heat treatment of a stabilizer arm is unsuitable, there are some which are insufficient of intensity.</p> <p>Therefore, when use is continued in the state as it is, a stabilizer arm breaks, running stability is spoiled and there is a possibility that it may become impossible to run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unspecified (THT)	Semitrailer	2004~2005	23
Unspecified (FAW)	Semitrailer	2005~2006	6
TOTAL			29