

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-1953	DATE	Sep. 26, 2013
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2013 model year Cadillac SRX vehicles with 18 inch wheels and that have not had service that required removal and reinstallation of the wheels. These vehicles may experience loosening of the wheel nuts. If this occurs, a creaking, rattling or grinding noise may originate from the wheel area. A steering vibration may also be present. If unnoticed or ignored, one or more of the wheel lug nuts could detach, or fatigue. The wheel attachment studs may fracture. If this happens while the vehicle is moving, a crash could result without prior warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T166C	「SRX」	2013	86
		TOTAL	86