

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1968	DATE	Sep. 25. 2013
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In some cases the threaded fastener of the side stand can work loose. If this remains unnoticed by the rider, the consequence is that the side-stand switch is not tripped when the side stand is extended/ retracted. There is a possibility of the engine refusing to start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C650GT	BMW C650GT	2012-2013	112
C600S	BMW C600S	2012-2013	116
		TOTAL	228