

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-1963	DATE	Sep. 25. 2013
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The fastener of the side-stand switch is not sufficiently secure. In isolated cases, over the vehicle's life span the side-stand switch can work loose and subsequently suffer damage. If the side-stand switch is not working reliably the engine does not shut down when a gear is engaged with the side stand extended.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
F700GS	BMW F700GS	2012-2013	178
F800GS	BMW F800GS	2012-2013	135
		TOTAL	313