

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3230	DATE	September.24.2013
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>With regard to the differential carrier on rear / front axle of heavy-duty truck with low platform, due to the inappropriate play on the spline at front side of the differential carrier, there may be excessive force toward the flange bolts which fixed the flange and spline shaft to be loaded.</p> <p>The continuous use in this condition may result in a damage of the bolt, and in the worst case, the flange will come off with propeller shaft allowing the vehicle down on the road.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-CG27G	Big Thumb	2002 – 2005	15
KL-CX27G	Big Thumb	2003 – 2005	34
ADG-CG2YA	Quon	2004 – 2006	21
		2006 – 2010	42
ADG-CG2ZA	Quon	2004 – 2006	62
		2006 – 2010	75
ADG-CX2YA	Quon	2004 – 2006	13
		2006 – 2010	19
LKG-CG5ZL	Quon	2010 – 2011	45
LKG-CG5ZA	Quon	2010 – 2011	16
LKG-CG5ZE	Quon	2011	1
TOTAL			343