

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3218	DATE	September 13,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Since the strength of the welding portion in the clutch master cylinder is insufficient, the clutch master cylinder may break resulting in the fluid leakage. In case the fluid is leaked, the clutch will be inoperable causing the transmission gear unable to change, and the vehicle unable to start once the vehicle comes to a stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-CZ4A	「LANCER EVOLUTION」	2007~2013	3,373
		TOTAL	3,373