

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3226	DATE	September. 12. 2013
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For front brake, the inner wire might have been cast into the cable end at an improper position. Through frequent repetition of the parking lever operation for the purpose of stopping or parking on a slope or the like, the cable end could be damaged, rendering the front brake ineffective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-JA07	SUPER CUB 110PRO	2009～2012	8,176
	SUPER CUB 110MD	2009～2011	32,872
		TOTAL	41,048