

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3222	Date	9th September ,2013
Manufacture	CATERPILLAR JAPAN LTD.		
Description of Deffect	The timing wheel bolts may be looson. The bolts might be tightened with low torque.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-SAT	「910H」	2011-2012	184
		TOTAL	184