

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 1961	Date	Sep. 6,2013
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )		
Description of defect	<p>The CAC assembly on XF and XJ 2.0L GTDi gasoline 2013 Model Year vehicles is made up of two flexible hoses and central metal resonator. As a result of supplier manufacturing process capabilities and incorrect design tolerances the hose to resonator joint may not be fully secure. The position of one of the flexible hoses and the associated hose clip can be incorrectly located during the CAC assembly process and the joint clip may not achieve the required clamp load. When the CAC assembly is subjected to high boost pressures, for example during vehicle acceleration, the hose clip may not retain the hose and the joint subsequently may separate. The driver may hear a loud pop noise as the joint separates and the engine may cut out.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-J12PB	「Jaguar XJ Luxury」	2013	34
CBA-J05PC	「Jaguar XF Prem. Lux」	2013	177
Total			211