

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3219	DATE	September 5 ,2013
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	Regarding the automatic transmission for the route busses, the return springs loaded for the shift valves in the valve body are not strong enough. For this reason, if the buses are kept in service, any of the return springs will be broken. This will hamper the gear shifting, and there is a possibility that the gear will be stuck in neutral and the bus will be unable to depart in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
PJ-LV234L1	「ERGA」	2006	4	
PDG-LV234L2		2007-2010	133	
LDG-LV234L3 LKG-LV234L3 QDG-LV234L3 OKG-LV234L3		2010-2012	187	
PJ-LV234N1		2005-2006	12	
PDG-LV234N2		2007-2010	86	
LDG-LV234N3 LKG-LV234N3 QDG-LV234N3 OKG-LV234N3		2010-2012	58	
LDG-LV234Q3 QDG-LV234Q3 OKG-LV234Q3		2011-2012	10	
		TOTAL	490	