

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3217	DATE	Sep. 5 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>① In some small trucks and busses equipped with a dual-clutch mechanical automatic transmission, the fastening force of the oil cooler hose at the connection to the transmission is not sufficient. If the vehicle continues to be used under this condition, the hose may come off and cause transmission oil leakage, making it impossible to shift gears and drive the vehicle.</p> <p>② In some small trucks and large busses, the locking mechanism in the driver's or passenger's seat belt winding device has a defect of the press-fit part becoming loose due to an inappropriate manufacturing method. This may cause an abnormal noise or sticking when fastening or releasing the seat belt. If the vehicle continues to be used in this condition, the press-fit part may come off, in the worst case, causing a failure of the seat belt to be locked in the event of a crash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FBA00	「FUSO CANTER」	2012	1
SKG-FBA20		2010～2011	2
SKG-FBA30		2010	1
SKG-FEA50		2011	1
SKG-FEB50		2011～2011	2
SKG-FEB90		2011	1
SKG-FGA20		2011	1
TKG-FBA20		2012～2013	1,557
TKG-FBA30		2012～2013	776
TKG-FBA50		2013～2013	209
TKG-FBA60		2012～2013	1,424
TKG-FDA20		2012～2013	143
TKG-FDA40		2012～2013	79
TKG-FEA20		2012～2013	331
TKG-FEA50		2012～2013	1,659
TKG-FEA80		2012～2013	179
TKG-FEB20		2012～2013	92
TKG-FEB50		2012～2013	1,592
TKG-FEB80		2012～2013	704
TKG-FEB90		2012～2013	865
TKG-FEC90		2012～2013	34
TKG-FGA20		2012～2013	127
TKG-FGB70		2012～2013	92
TPG-FBA00		2012～2013	986
TPG-FBA20		2012～2013	19
TPG-FBA50		2013	1
TPG-FDA00		2012～2013	333

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-FDA20	「FUSO CANTER」	2012～2013	2
TPG-FDA40		2012	1
TPG-FEA20		2012～2013	30
TPG-FEA50		2012～2013	9
TPG-FEA80		2012～2012	2
TPG-FEB20		2012～2013	7
TPG-FEB50		2012～2013	33
TPG-FEB80		2012～2013	5
TPG-FEB90		2012～2013	13
TPG-FGA20		2012～2013	2
TQG-FEA13		2012～2013	17
TQG-FEA53		2012～2013	155
TQG-FEB73		2012～2013	179
TRG-FBA00		2012～2013	15
TRG-FDA00		2012～2013	7
TPG-BE640G	「FUSO ROSA」	2012～2013	218
TPG-BE640J		2012～2013	40
TRG-BE640J	「FUSO ROSA」	2012	1
QDG-MM96FH	「FUSO AERO ACE」	2012～2013	11
QRG-MS96VP		2012～2013	301
QRG-MS96VP	「FUSO AERO QUEEN」	2012～2013	34
TDG-MM96FH	「FUSO AERO ACE」	2012～2013	31
TKG-FBA3W	「ATLAS」	2013～2013	13
TKG-FBA5W		2013～2013	23
TKG-FEA5W		2013～2013	14
TKG-FEB5W		2013～2013	14
TKG-FGB7W		2013	1
TPG-FBA2W		2013～2013	5
TPG-FBA5W		2013～2013	5
TPG-FBA6W		2013～2013	10
TPG-FDA2W		2013～2013	6
TPG-FDA4W		2013～2013	3
TPG-FEA2W		2013～2013	6
TPG-FEA5W		2013～2013	8
TPG-FEB2W		2013～2013	11
TPG-FEB5W		2013～2013	4
TPG-FEB8W		2012～2013	34
TPG-FEB9W		2013～2013	10
TPG-FGA2W		2013～2013	5
TPG-FGB7W		2013	1
		TOTAL	12,497