

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	GAI-1948	DATE	July 18,2013
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive ASIA Pte Ltd)		
DESCRIPTION OF DEFECT	Because water leaks into the alarming horn from the opening area due to the unsuitable installation position of the left and right alarming horn, the sound quality has degraded, either or both of the alarming horns do not operate as a result of water entering the electronic circuit and there is a possibility that this may breach the Article 43 Safety Standards. The left and right alarming horn will be newly replaced and the installation method will be changed		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MP4-12C	「McLaren MP4-12C」	2012-2013	54
ABA-MP4-12CS	「McLaren MP4-12C Spider」	2013	22
		TOTAL	76