

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-1951	DATE	July. 09. 2013
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that in isolated instances, data are not saved correctly in the instrument panel after the ignition is switched off or after under voltage events. This can lead to errors (e.g. incorrect on-board computer readings). There is also a possibility of the key data saved in the instrument panel being corrupted, which could mean that one or more ignition keys are no longer recognized (electronic immobilizer is not deactivated). The problem is due to a software bug.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C600S	BMW C600Sport	2012-2013	257
C650GT	BMW C650GT	2012-2013	333
		TOTAL	590