

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3250	DATE	Oct. 31 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	Some service part change levers for heavy- and medium-duty buses were fabricated improperly. If the lever installed to the vehicle is continued to be used as it is, the lever may break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
P-MK117J	「FUSO AERO MIDI」	1990	1
P-MM527H	「FUSO AERO BUS」	1988~1989	4
P-MP218M	「FUSO AERO STAR」	1989~1989	2
P-MP618K		1989~1990	2
P-MS725S	「FUSO AERO BUS」	1990	1
P-MS725SA		1990	1
P-MS729S	「FUSO AERO QUEEN」	1988~1990	4
	「FUSO AERO BUS」	1989~1989	2
P-MS729SA		1990~1990	3
U-MJ527F	「FUSO AERO MIDI」	1990~1992	5
U-MK516J		1993	1
U-MK526J		1992	1
U-MM526H	「FUSO AERO BUS」	1991~1993	3
U-MP218K	「FUSO AERO STAR」	1991~1994	3
U-MP218M		1991~1994	7
U-MP618K		1993	1
U-MP618M		1994~1995	4
U-MS726N	「FUSO AERO BUS」	1992	1
U-MS726S		1992~1993	2
U-MS729S	「FUSO AERO QUEEN」	1991~1992	3
	「FUSO AERO BUS」	1990~1993	10
U-MS729SA		1991~1992	5
U-MS821P	「FUSO AERO QUEEN」	1992~1995	17
	「FUSO AERO BUS」	1993~1995	4
U-MS821PA	「FUSO AERO QUEEN」	1993~1995	4
	「FUSO AERO BUS」	1993~1995	3
1994~1995		2	
1992~1995		6	
U-MU525TA	「FUSO AERO QUEEN」	1992	1
KC-MP217K	「FUSO AERO STAR」	1997	1
KC-MP217M		1996	1
KL-MS86MP	「FUSO AERO QUEEN」	2001	1
	「FUSO AERO BUS」	2005	1
TOTAL			107