

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

| | | | |
|------------------------------|--|------|-----------------|
| CAMPAIGN No. | Gai-1978 | DATE | 31/October/2013 |
| MANUFACTURER | Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited) | | |
| DESCRIPTION OF DEFECT | Software bugs in the Central Electronic Module (CEM) causing increased quiescent current leading to a drained battery. Due to a software deviation the CEM may not perform as intended causing drainage of the battery. If this deviation occurs and depending on the state of battery charge, may experience one or more of the following symptoms, difficult to open the vehicle with the remote key and difficult to start the engine. The repair is to update the software of the CEM, and reset the battery monitoring sensor. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------|-----------------|---------------------|-------------------|
| VOLVO | [S60] | 2014 | 12 |
| | [V70] | 2014 | 14 |
| | [XC70] | 2014 | 2 |
| | [V60] | 2014 | 26 |
| | [XC60] | 2014 | 23 |
| | | TOTAL | 77 |