

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1971	DATE	October 25, 2013
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	Due to insufficient strength of diaphragm inside the brake master VAC, the diaphragm may be deformed over time. This then prevents the brake pedal from returning to its rest position and eventually causes unintentional braking application and the brake lamp remained lit on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T85F02	PEUGEOT 3008	2012 - 2013	73
		TOTAL	73