

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3254	DATE	October.24. 2013
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For vehicles equipped with 7-speed dual-clutch automatic transmission (DCT), the automatic transmission control computer may have been programmed improperly and thereby the transmission dog and sleeve may not be fully engaged while stopping in the motor driving mode. Should this happen, the transmission warning light would blink and the meter display would indicate the need for servicing and, engagement failure of the 1st gear could disable the vehicle from starting to move or engagement failure of the 2nd gear could necessitate driving only in the odd-numbered shift gears.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-GP5	FIT	2013	4,883
		TOTAL	4,883