

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3242	DATE	17 October 2013
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO, LTD.		
DESCRIPTION OF DEFECT	<p>The fixing hole in a reduction gear of a load roller is defective. The hole holds a spring pin that retains a planetary pin, which fixes a planetary gear. Hence, the spring pin can slip off when the vehicle is traveling. If the machine is used continuously as it is, the planetary pin becomes loose, and the position of the planetary gear becomes off to the original position. Then, the gear becomes unable to be engaged with other gears and breaks. In the worst case, wheels are locked and the vehicle becomes unable to travel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF	REMARKS
-	「CC135C-3A」	2008	38	
-	「HW30VWH-2」	2008	4	
-	「CC150C-3A」	2008	52	
-	「HW41VWH-2」	2008	6	
SB-CP210	「CP210」	2008	37	
SB-21A0	「HN210WHH」	2008	5	
SC-CP215	「CP215」	2008	8	
SC-21B0	「HN215WHH」	2008	2	
KDP-CP220	「CP220-3」	2008	6	
<b>T O T A L</b>			158	