

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3237	DATE	October.4.2013
MANUFACTURER	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	There is a possibility that it becomes impossible to drive the vehicle, for the selection mistake of the screws which tightened reduction gears and a universal joint, in the drive trains.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-NR40A	NR401	2008~2013	10
NR60A	NR601	2010~2012	5
NR60A	NRZ601	2011	1
		TOTAL	16