

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3236	DATE	October.4.2013
MANUFACTURER	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	There is a possibility that it becomes impossible to drive the vehicle, for the lack of a vent hole which machined a universal joint, in the drive trains.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-NR6A	NR282	2012/2013	12
JDS-NR6A	NR301	2012/2013	24
JDS-NR6A	NRNS302	2013	1
TOTAL			37