

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1988	DATE	November 21 st 2013
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The joint disc is connecting the transmission and propeller shaft. Due to the possible installation of faulty joint disc, this joint disc may become deformed when the vehicle is in motion and may cause noise. When continuing driving under this situation, in worst case, the joint disc might break, drive force cannot be transmitted and driving might become impossible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LW30	「BMW 640i Cabriolet」	2010	57
		TOTAL	57