

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1987	DATE	November 20, 2013
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Atlantic Cars Limited, Shintoyo Enterprises Ltd, Hakko LR Co., Ltd.)		
DESCRIPTION OF DEFECT	Because the material on the throttle lever did not meet the required standard, the throttle lever could be broken and come off on the continued use. If the throttle lever is come off, the throttle pedal cannot be pushed on and the car cannot be accelerated. Also, the throttle lever can be more easily broken on Left hand Drive cars because there are the cars on Left hand Drive cars that scuff plate can be touched to throttle pedal due to the poor fitting of scuff plate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	DB9 Coupe, DB9 Volante	2007-2013	59

	V8 Vantage Coupe, V8 Vantage Roadster, V8 Vantage S Coupe, V8 Vantage S Roadster	2007-2013	71
	Virage Coupe, Virage Volante	2011-2012	16
	DBS Coupe, DBS Volante	2008-2012	22
	V12 Vantage Coupe, V12 Vantage Roadster, V12 Zagato	2009-2013	17

	Rapide, Rapide S	2010-2013	66
		TOTAL	251