

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3259	DATE	Nov. 8, 2013
MANUFACTURE	Caterpillar Japan LTD		
DESCRIPTION OF DEFECT	Existing muffler bracket assembly which connects turbocharger and muffler may not have sufficient durability to keep turbocharger in place when burst. Replace the muffler bracket assembly with more robust ones to prevent possibility of fire caused by turbocharger burst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2SR	「980G」	1997-1998	2
		TOTAL	2