

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3258	DATE	November 8,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the affected vehicles equipped with 4B10 engine, since the programming of the engine ECU is inappropriate, the air volume may become insufficient or the air fuel ratio may become too lean at idling which could result in the engine stall at around the idling speed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GA3W	「RVR」	2010～2012	18,271
DBA-CX3A	「GALANT」	2009～2011	1,477
DBA-CY3A		2009～2011	2,871
		TOTAL	22,619