

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3257	DATE	Nov. 8, 2013
MANUFACTURE	Caterpillar Japan LTD		
DESCRIPTION OF DEFECT	<p>Electrical harness between battery and engine starting motor may interfere with other parts in machine frame due to inadequate routing. The harness can be damaged due to interference, and it can cause short circuit. In worst case, there's possibility of fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
AYT	「980G II」	2003-2005	2
		TOTAL	2