

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3261	DATE	Nov.7.2013
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In valve springs of the engine, due to the improper control of the surface treatment process, there is a possibility that some valve springs have corrosion on the surface. In this condition, the spring could break originating from the corroded portion during the vehicle usage, causing rough engine performance. In some cases, the engine could stop while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABG-TRC600M	[HINO Dutro]	2013	1
ABG-TRC600	[Toyota Dyna 200] [Toyota Toyoace G25]	2013	5
		TOTAL	6