

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1982	DATE	November. 7. 2013
MANUFACTURER	Sundiro Honda Motorcycle Co., Ltd.		
DESCRIPTION OF DEFECT	For front brake, the inner wire might have been cast into the cable end at an improper position. Through frequent repetition of the parking lever operation for the purpose of stopping or parking on a slope or the like, the cable end could be damaged, rendering the front brake ineffective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-AA04	SUPER CUB 50 PRO	2012~2013	10,762
	SUPER CUB 50 MD	2012	1,582
EBJ-JA10	SUPER CUB 110 PRO	2012~2013	2,657
	SUPER CUB 110 MD	2012	6,218
	CROSS CUB 110	2013	1,679
		TOTAL	22,898