

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1970	DATE	Nov. 6, 2013
MANUFACTURER	AUDI AG (Japanese Importer : Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Technical background;</p> <p>On Audi A8/A8L/S8 vehicles with glass sliding sunroof manufactured within a specific period, an unfavorable stress distribution was set up in the glass roof panel during production. This can cause the glass panel to break unexpectedly. This usually happens when a door is slammed closed while the vehicle is stationary. The panel consists of single-layer safety glass, which crumbles into small pieces in the event of breakage. A slight risk of injury caused by falling pieces of glass cannot be entirely ruled out.</p> <p>Remedy;</p> <p>The production year/month of the glass sliding roof panel must be checked on the affected vehicles and the panel must be replaced if necessary.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-4HCGWF	A8 3.0	2013	1
ABA-4HCEUF	A8 4.0	2013	9
ABA-4HCEUL	A8L 4.0	2013	8
ABA-4HCGTF	S8	2013	11
		TOTAL	29