

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1969	DATE	Nov. 6, 2013
MANUFACTURER	AUDI AG (Japanese Importer : Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Technical background; Due to manufacturing tolerances, the fuel line may become damaged in individual cases after a period of time on Audi S6 and S7 vehicles manufactured within a specific period. In the worst case, this can cause leakage.</p> <p>Remedy; The fuel line must be replaced and an additional retainer is installed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-4GCEUA	S6, S6Avant	2013 – 2014	206
ABA-4GCEUL	S7	2013 – 2014	189
		TOTAL	395