

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3282	DATE	December,25,2013
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to misassemble of piston seals, which is installed to steering cylinder of rear axle. Therefore, if a machine is continuously used under the above condition, oil leak from the steering cylinder and there is a possibility that an operator cannot control steering.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M239	「FB15ML」	2013	1
		TOTAL	1