VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	GAI-2001	DATE	December 25, 2013
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	This replacement is necessary since the wiring harness may not be in conformance. The continuous use of a vehicle equipped with non-conforming wiring harness may lead to electrical anomalies such as vehicle's brake down and, in more severe cases, also to smoke from engine compartment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MQP38A	「Quattroporte GTS」	2013	15
		TOTAL	15