

VEHICLES SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1993	DATE	December 25.2013
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	The tightening force of the differential bolts varied widely. There is possibility of out of range of proper tightening force.The bolts which are out of range of proper tightening force would be loosening. Using without any remedy, it would be broken and course that the vehicle can not run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「JD-6130R」	2012	1
-	「JD-6230」	2011.2012	35
-	「JD-6330」	2011.2012	61
-	「JD-6430」	2011.2012	127
-	「JD-6630」	2011.2012	56
TOTAL			280