VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN NO.	3279	DATE	December ,19,2013
MANUFACTURER	MITSUBISHI AGRICULTURAL MACHINERY CO.LTD.		
DESCRIPTION OF DEFECT	There is the risk the tractor cannot stop in reverse shift position in the case of operation immediately after start of the engine due to the fault in programming of traveling control system build in the tractor. If operator shifts power shuttle lever into reverse position immediately after start of the engine, tractor might continue to travel even after depressing the brake pedal. This might be caused from bigger drive force of reverse clutch overcoming the braking force due to such fault in program.		
ТҮРЕ	COMMERCIAL	MODEL	NUMBER OF
	NAME	YEAR RECALLED	VEHICLE
E DM-G T 3 6 C	「GA30」	$2 \ 0 \ 1 \ 3 \sim 2 \ 0 \ 1 \ 3$	2
	「GA36」		1
	「GA36H」		1
E DM-G T 4 6 F	「GA41」		3
	「GA46」		5
EDM-GT50D	「GA50」		6
		TOTAL	18