

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3271	DATE	Dec.17 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty buses, the processing of the slit in the cover for the driver's seat belt retractor was improper. If the seat belt continues to be used in this condition, its webbing may be caught and damaged by the edge of the slit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-MS96JP	「FUSO AERO ACE」	2007～2008	129
BKG-AS96JP	「SPACEARROW A」	2008～2008	6
		TOTAL	135