

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|---|------|------------|
| CAMPAIGN No. | Gai-1996 | DATE | 2013/12/17 |
| MANUFACTURE | Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | On model series 222, in very rare individual cases the connections of the belts to the front seats may possibly not be installed correctly. As a result, on a small batch of vehicles it cannot be completely ruled out that the restraint effect could be impaired with extremely high loads. We therefore ask that you check the connections on the affected vehicles and install them correctly, if necessary. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------------|-----------------|---------------------|-------------------|
| DBA-222182 | S550 | 2013 | 34 |
| DBA-222182C | S550 | 2013 | 6 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | TOTAL | 40 |