

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 2 6 9	DATE	Dec.12.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>The return speed of the cable linking the outside handle to the door lock in the rear door may become slower than the outside handle, the cable may not return to the locking position after the outside handle operation. As the result, the rear door cannot be closed or, in an extreme case, the rear door may rarely open during the driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HGY 5 1	N I S S A N 「C I M A」	2 0 1 2 ~ 2 0 1 3	2, 6 0 4
DAA-BHGY 5 1	M I T S B I S H I 「D I G N I T Y」		7 8
		TOTAL	2, 6 8 2