## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1986	DATE	Dec. 4, 2013	
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)			
	Technical background			
	On the rear axle of vehicles fitted with carbon ceramic brakes, the stainless steel			
DESCRIPTION OF	screws fixing the rotor to the metal bell may fail due to stress corrosion cracking if			
	the vehicle has been used in extreme salt environments.			
DESCRIPTION OF DEFECT				
	Remedy			
	On the affected vehicles, the fasteners securing the rear ceramic brake discs must be			
	replaced with new fasteners in accordance with the Repair Instructions. The new			
	fasteners utilise a material tolerant in this application.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BCBWR	Continental GT		
ABA-BSBWR	Continental GT Speed	2007 2010	
ABA-BDBWR	Continental Flying Spur Speed 2007 – 2010		50
ABA-BCCKH	Continental Supersports		
		TOTAL	50