

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1985	DATE	Dec. 4, 2013
MANUFACTURER	AUDI AG (Japanese Importer : Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Technical background; On vehicles fitted with carbon ceramic brakes, the stainless steel screws fixing the rotor to the metal bell may fail due to stress corrosion cracking, if the vehicle has been used in extremely salty environments.</p> <p>Remedy; On the affected vehicles the fasteners on the ceramic brakes must be replaced with improved fasteners in accordance with the Repair Instructions.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-4EBSMF	S8	2007 – 2010	123
		TOTAL	123