VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2008	DATE	January 31 st , 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On the instrument panel trim, the processing of the surface skin is missing, so that the front passenger airbag might not deploy appropriately. And, this might lead to unexpected spinning of the instrument panel trim parts. In worst case, the occupant might get injured by the spinning parts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-WX20	「BMW X3 xDrive 20i」	2012-2013	2
		TOTAL	2