

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3290	DATE	January.27.2014
MANUFACTURER	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	There is a possibility that it becomes impossible to drive the vehicle, because the hydraulic pump attached to the engine does not drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS - NR6B	NR302	2013	56
UDS - NR6A	NRN302	2013	1
		TOTAL	57